



## Service History Report

KIP-860

KTA-SYS860K

Serial Number: 13561642

Service Date	Actions Taken
10/16/17	UNCRATE AND SETUP PRINTER.
10/17/17	FINISHED CALIBRATING PRINTER. REPLACED CLEANING MOTOR ON Y. WENT OVER TRAINING.
10/23/17	UPDATED SOFTWARE AND FIRMWARE. INSTALLED ESAS.
1/29/18	REMOVE FUSER JAM AND TEST.
3/6/18	PM SERVICE ON MACHINE.
4/25/18	PM SERVICE ON MACHINE.
5/8/18	UPDATED SOFTWARE AND FIRMWARE.
6/5/18	PM SERVICE ON MACHINE.
7/24/18	PM SERVICE ON MACHINE. REPLACE ONE WIRE.
2/21/19	PM SERVICE ON MACHINE.
4/5/19	PM SERVICE ON MACHINE. REPLACE ONE WIRE.
4/23/19	REMOVED UPPER FUSER NAIL ASSEMBLY. ADJUSTED NAILS AND RESEATED SOME NAIL SPRINGS. CLEANED SCANNER GLASS.
6/14/19	PM SERVICE ON MACHINE.
7/24/19	REPLACED FUSER WEB.
7/30/19	PM SERVICE ON MACHINE.
8/30/19	REMOVED PAPER JAM. INVESTIGATE FUSER NAILS. REWRAP SPRING AND REINSTLL ON MONITOR SIDE OF FUSER. ADJUSTED ALL FUSER NAILS.
11/25/19	PM SERVICE ON MACHINE.
5/29/20	REMOVED FUSER AND LUBRICATED FUSER DOOR.