



Service Date

11/1/17

12/8/17

5/10/18

7/10/18

9/28/18

12/14/18

1/2/19

1/29/19

2/19/19

4/17/19

4/19/19

5/10/19

7/8/19

8/19/19

9/30/19

11/25/19

12/9/19

1/24/20

2/19/20

2/25/20

3/10/20

3/24/20

3/30/20

Service History Report

KIP-880

KTA- SYS880K

Serial Number: 13572079

Actions Taken

UNCRATED SCANNER AND PRINTER
SETUP BOTH

BACKED UP SETTINGS. CONNECTED SCANNER.

INSTALLED ORIGINAL DEV UNIT WITH NEW DRIVE BELT.

UPDATED FIRMWARE AND SOFTWARE. PM SERVICE ON PRINTER. CHANGED 1 WIRE.

REPLACED TENSION BELT.

REPLACED YELLOW DEV BELT.

PM SERVICE ON PRINTER. CHANGED 3 WIRES.

REMOVED PAPER JAM.

PULLED WEB FRAME AND REPLACED IT

REPLACED BRACKET PINS.

CLEANED SCANNER GLASS.

CLEANED DEV SENSORS AND PRINthead.

REMOVED PAPER JAM IN FUSER EXIT. FIXED BENT NAILS.

PM SERVICE ON PRINTER. CHANGED 4 WIRES.

INSTALLED NEW WEB FUSER.

CLEANED SENSORS AND UPDATED FIRMWARE.

REMOVED BLACK DEV. ADDED SOME TONER SHIELDS. CLEANED OUT EXCESS TONER.

CLEANED BELT SKEW SENSORS, DENSITY SENSORS, EXCESS TONER AROUND DRUM AND PUT WHITE ROLLER BACK IN PLACE.

CLEANED UP TONER AND REPLACED GEAR ON BLACK DEV UNIT.

INSTALLED FUSER WIRING HARNESS, NEW THERMOSTATS AND THERMISTORS.

CLEANED SCANNER GLASS.

REMOVED PAPER JAM.

REATTACHED TENSIONER BRACKET.
